


Please tick in box - Is chamfer a visible top surface for priming YES NO



PRINTED COPY UNCONTROLLED

CUSTOMER TO CONFIRM DIMENSIONS A+B+C INCLUDING PRODUCT WIDTH AND THICKNESS.
WHEN DIMENSION C=0, ANGLED CUTTER MUST BE SET ON SIDE HEAD!

<p>SAM MOULDINGS</p> <p>Newpark Industrial Estate Greystone Road Antrim BT41 2DU Tel : (028) 9442 8288 Fax : (028) 9442 8244 Website: www.sammouldings.co.uk Email: info@sammouldings.co.uk</p>	PROFILE	DRAWN BY	M.KIRKPATRICK	REV:
	SP 601	DATE	23/5/00	AUTH:
		SCALE	1:1	TOLERANCE +/- 0.5MM