


Place SAM 01 profile block on side spindle 2.
 Place SP 1447T1 profile block upside down on side spindle 3.
 Place SAM 27 profile block on the first top spindle.
 Place SAM 4288 profile block on the last bottom spindle.



Dual Purpose SAM27/SAM4288

PRINTED COPY UNCONTROLLED

MOULDER	ANY
PASSES	1
DRAWN BY	Bart Sobecki
REV:	1
DATE	08/03/2023
AUTH:	
SCALE	1:1
TOLERANCE	+/- 0.5MM



Newpark Industrial Estate
 Greystone Road, Antrim
 BT41 2RU
 T: +44 (0)28 9442 8288 F: +44 (0)28 9442 8244
 E: team@samonline.co.uk
 W: www.samonline.co.uk

SAM 5378

PROFILE

DRAWN BY

Bart Sobecki

REV: 1

DATE

08/03/2023

AUTH:

SCALE

1:1

TOLERANCE
 +/- 0.5MM