


Place SP1447T1 profile block on side spindle 2.  
 Place SAM 01 profile block on side spindle 3.  
 Place SAM 4288 profile block on the first top spindle.  
 Place 5mm PCD groover on the last bottom spindle.



Dual Purpose SAM4288/SAM5059

PRINTED COPY UNCONTROLLED

MOULDER	ANY
PASSES	1
DRAWN BY	Bart Sobecki
DATE	08/03/2023
SCALE	1:1
REV:	1
AUTH:	
TOLERANCE	+/- 0.5MM



Newpark Industrial Estate  
 Greystone Road, Antrim  
 BT41 2RU  
 T: +44 (0)28 9442 8288 F: +44 (0)28 9442 8244  
 E: team@samonline.co.uk  
 W: www.samonline.co.uk

SAM 5379

PROFILE

DRAWN BY

Bart Sobecki

REV: 1

DATE

08/03/2023

AUTH:

SCALE

1:1

TOLERANCE  
 +/- 0.5MM