


Place SAM 01 profile block on side spindle 2.
 Place SAM 01 profile block on side spindle 3.
 Place Adjustable Groover on the first top spindle set bigger than Dim A, to produce rebate.

Please tick in box - Is rebate a visable top surface for priming YES NO



CUSTOMER TO CONFIRM DIMENSIONS A+B+C INCLUDING PRODUCT WIDTH AND THICKNESS

PRINTED COPY UNCONTROLLED

SAM MOULDINGS

Newpark Industrial Estate Greystone Road Antrim BT41 2DU
 Tel :(028) 9442 8288 Fax :(028) 9442 8244

Website: www.sammouldings.co.uk Email: info@sammouldings.co.uk

PROFILE

SP 603

DRAWN BY

M.KIRKPATRICK

REV:

DATE

23/5/00

AUTH:

SCALE

1:1

TOLERANCE
 +/- 0.5MM